OF AGRICULTURE OF AGR

BUREAU OF ANIMAL INDUSTRY

GENERAL PROCEDURES

Document Name:

CALIBRATION OF EQUIPMENT

GP BAI-21

Rev. No.: 01 November 8, 2017

Page: 1/2

1.0 Objectives

- To ensure that measuring equipment are adjusted and calibrated against measurement standards traceable to international measurement standards.
- To develop the calibration plan for all measuring and monitoring equipment

2.0 Scope

• This procedure covers all activities pertaining to the calibration of all measuring equipment and monitoring of actions taken.

3.0 Definition of Terms

• CSP - refers to Calibration Service Provider

4.0 Records

- Equipment Folder (Daily PM checklist, PM Checklist, Breakdown Report, PM Report/Calibration Certificate, Operation's Manual)
- R-BAI-11 Calibration Report File

5.0 References

6.0 Process Flow

PROCESS	RESPONSIBILITY	DETAILS
Check/Review Calibration Plan	SH/UH/Analyst/ Specialist	SSC/USC to oversee schedule base on the PL- BAI 04 Calibration Plan
Prepare request for Calibration	SSC/USC	 Requests shall be done ahead of time prior to the scheduled date of calibration to give ample time for processing. Service Provider should be PAB accredited
Perform Calibration	SSC/USC Concerned Service Provider	Inform EC

OF AGRICULTURE RE

BUREAU OF ANIMAL INDUSTRY

GENERAL PROCEDURES


Document Name:

GP BAI-21

CALIBRATION OF EQUIPMENT

Rev. No.: 01 November 8, 2017

Page: 2/2



Reviewed by:	Approved by:
ENGRALEDNICIO VENTOCILLO	RONNIE D. DOMINGO, DVM MSc
Equipment Custodian	Top Management